IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of

Arnold M. FRISCH

Patent No: 7,171,601

Issued: January 30, 2007

For: PROGRAMMABLE JITTER GENERATOR

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 CFR 1.322(a))

COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450

Attention:

Patent Issue Division

Decision and Certificate of Correction Branch

Sir:

It is requested that a Certificate of Correction be issued in accordance with the enclosed form PTO-1050.

The column and line numbers where the errors occur in the issued patent are specified below. The source of the correction is indicated in parentheses following the correction.

Column 8

Line 50, "a the jittery test signal" should be --the jittery test signal--. (Reply to the Office Action Mailed 01/09/2006, amendment for claim 1)

Column 9

Line 31, "function of delay" should be --function of the delay--. (Claim 10 as originally filed)

Column 10

Line 59, "(TC)" should be --(IC)--. (Claim 22 as originally filed)

Column 12

Line 8, "signal to with a delay" should be --signal with a delay--. (Reply to the Office Action Mailed 01/09/2006, amendment for claim 31).

This patent is assigned of record to Credence Systems Corporation, the assignment having been recorded on November 20, 2003 at Reel 014147, Frame 0116.

This request is made by the undersigned as attorney for the patentee/assignee under the Power of Attorney that was signed on August 21, 2003 and is of record in the Patent and Trademark Office.

Please send the certificate to the address indicated below.

Respectfully submitted,

/John Smith-Hill/ John Smith-Hill Reg. No. 27,730

SMITH-HILL & BEDELL, P.C. 16100 N.W. Cornell Road, #220 Beaverton, Oregon 97006 (503) 574-3100 Docket: CRED 2779

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,171,601

DATED : January 30, 2007 INVENTOR(S) : Arnold M. Frisch

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8

Line 50, "a the jittery test signal" should be --the jittery test signal--.

Column 9

Line 31, "function of delay" should be --function of the delay--.

Column 10

Line 59, "(TC)" should be --(IC)--.

Column 12

Line 8, "signal to with a delay" should be --signal with a delay--.

MAILING ADDRESS OF SENDER:

PATENT NO. 7,171,601 ATTORNEY DOCKET CRED 2779

SMITH-HILL AND BEDELL, P.C. 16100 N.W. Cornell Road, #220 Beaverton, Oregon 97006